


WWW. BROKENBOLTS.COM 757-465-0333





That's not mud around the studs it is the metal removed by Disintegration

Traveled Monday

Removed a 5mm tap in the shop on Tuesday. Just 4 days at CBG, LLC



